



# **Grants Mining District**

**2015 – 2020 Five-Year Plan Update**



## Objectives of the 2015 - 2020 Five-Year Plan

- Assess Water Supply Sources for Contamination
- Assess and Cleanup of Legacy Uranium Mine Sites
- Assess, Cleanup, and Perform Long-Term Management of Former Uranium Milling Sites
- Assess and Clean Up Contaminated Structures and Properties
- Communicate and Coordinate with Communities



## 2015 – 2020 Five-Year Plan Progress


- Phase 1 Ground Water Report Released (Sept 2016)





## 2015 – 2020 Five-Year Plan Progress

- Removal Assessment Completed for Eastern Ambrosia Lake Area (March 2016) and EE\CA being Prepared
- Removal Assessment Started on Western Ambrosia Lake Area and Nearing Completion







## 2015 – 2020 Five-Year Plan Progress

- NM MMD Completed Reclamation of Spencer Mine (May 2016)
- USFS Completed Removal Actions at 4 Mines (July 2016)





## 2015 – 2020 Five-Year Plan Progress

- NMED\NMEMNRD Released “Joint Guidance for the Cleanup and Reclamation of Existing Uranium Mining Operations in New Mexico”

### Joint Guidance for the Cleanup and Reclamation of Existing Uranium Mining Operations in New Mexico



Energy, Minerals & Natural Resources Department  
Mining and Minerals Division  
1220 South St. Francis Drive  
Santa Fe, NM 87505

and

New Mexico Environment Department  
Mining Environmental Compliance Section  
1190 South St. Francis Drive  
Santa Fe, NM 87505



March 2016



## For More Information

- Grants Outreach Center
  - 825 E Santa Fe Ave. Grants, NM
  - 505.285.5395 or 505.285.5396
- Grants Mining District Coordinator
  - Kevin Shade
  - shade.kevin@epa.gov
  - 214.665.2708 or 800.887.6063
- Ambrosia Lake Outreach Center
  - 1½ mile South of NM 509 / NM 605 Junction
- Community Involvement Coordinator
  - Adam Weece
  - weece.adam@epa.gov
  - 214.665.2264 or 800.887.6063
- Website: <https://www.epa.gov/grants-mining-district>